



Pupil Accommodation Review
Maplewood HS, Sir R L Borden BTI, Sir W Laurier CI & West Hill CI

Facility Profile	Maplewood HS	Sir Robert L Borden BTI	Sir Wilfrid Laurier CI	West Hill CI
Address	120 Galloway Rd, Scarborough, ON, M1E1W7	200 Poplar Rd, Scarborough, ON, M1E1Z7	145 Guildwood Pky, Scarborough, ON, M1E1P5	350 Morningside Ave, Scarborough, ON, M1E3G3
Year Built	1967	1965	1964	1958
Building Age	48	50	51	57
Site plan and floor plan (Appendix A)	Pg. 1	Pg. 4	Pg. 7	Pg. 11
School attendance area (Appendix A)	Pg. 14			
Aerial Photo (Appendix A)	Pg. 15	Pg. 16	Pg. 17	Pg. 18
Development Map (Appendix A)	Pg. 20			
Site Size Acres	12.60	11.90	13.90	17.10
Facility Size Sq Ft	115,477	142,579	236,094	217,013
Sq Ft per Pupil Place	200	167	167	154
Portables on Site 31 October 2014	0	4	4	0
Number and type of Instructional rooms (Appendix A)	Pg. 20	Pg. 22	Pg. 25	Pg. 29
Soft Surface (Green) Play Fields	4.37	5.00	5.60	6.60
Parking (Main + Ancilliary)	1.09	0.88	0.92	2.15
Non-Parking Circulation/Paved	0.84	1.34	1.24	0.98
Projected five-year facility renewal needs (Appendix A)	Pg. 32	Pg. 33	Pg. 34	Pg. 35
Facility Condition Index 2014	17%	14%	18%	18%
Facility Condition Index 2018	97%	81%	83%	87%
Facility Condition Index 2023	106%	106%	92%	113%
Average Walking Distance to School (M)	-	-	3445	3851
Percentage of Students Eligible for Transportation	76%	1%	0%	44%
Length of bus ride to the school (Longest)	62 MIN	57 MIN	N/A	46 MIN
Length of bus ride to the school (Shortest)	11 MIN	20 MIN	N/A	9 MIN
Length of bus ride to the school (Average)	42 MIN	36 MIN	N/A	25 MIN
Number of Parking Spaces	114	153	168	198
Adequacy of parking (Technical Condition)	N/A	Fair	Poor	Poor
Barrier-free Accessibility (Appendix A)	Pg. 40	Pg. 43	Pg. 46	Pg. 49
Facility Capacity (OTG)	576	852	1416	1407
Actual Enrolment 31 October 2014	206	281	1427	760
Surplus/Shortage of Pupil Places	370	571	-11	647